

DATE

~~TOP SECRET~~1
2
3
4
5
6
7
8

ROUTING

9
10
11
12
13
14
15
16TO :
FROM :
ACTION:
INFO :

IN 68594

TO ~~TOP SECRET~~ INFO 25X1A6a CITE 250647Z CITE 7418

25X1A2g

INFO

25X1A6a

25X1A2g

1. RACK INSTALLED IN OPERATIONS AREA ON 25 APR
AND FUNCTIONING NORMALLY USING CALIBRATION TAPE. ADD-
ITIONAL CHECKOUT AWAITING ARRIVAL OF INTERFACE CABLE
SHIPPED APO MAIL FROM [REDACTED] ON 21 APRIL. PRINTER WORKING
FINE.

25X1A5a1

25X1D0d

2. PRELIMINARY MONITORING OF THE [REDACTED]

[REDACTED] SHOWS NO STRONG INTER-

25X1D0d

FERRING SIGNALS.

25X1D0d

3. [REDACTED] HAS NOT REPEAT NOT BEEN

PUT ON AIR AS YET DUE TO EXERCISER EQUIPMENT NOT BEING
RECEIVED. ANTICIPATE HAVING THIS FORMAT ON AIR FOR FIRST
TIME ON [REDACTED]

25X1D0d

~~TOP SECRET~~ TOR: 251015Z APR 67~~TOP SECRET~~GROUP 1
EXCLUDED FROM AUTO-
MATIC DOWNGRADING
AND DECLASSIFICATION

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.